

FIG. 1




FIG. 2




Fig. 3

http://consulting.apexinteractive.com/request.jsp?LOGON=458vcdelay - Microsoft Internet Explorer

File Edit View Favorites Tools Help

http://consulting.apexinteractive.com/request.jsp?LOGON=458vcdelay

Consulting Request Wizard Sample Services Sample Reports Project Collaboration

92 94 96 98 99

The Consulting Request Wizard

Please fill out the following form. You will receive a response from GE within one working day.

102 104

1. What system or component is involved?

2. What is the plant's current operating condition?
(Feel free to select more than one condition)

☐ Normal Power Operation
☐ Ascension
☐ Reduced Power
☐ Hot Shut Down
☐ Cold Shut Down
☐ Refueling/Maintenance Outage
☐ Other

106

3. Do you know of prior or current GE work that may be useful for addressing this issue?

☒ No 108

If Yes, please provide a brief

Fig. 4




Fig. 5

